



VOLKSWAGEN POLO: CC0621			
Vinnumber:	<b>WVWZZZ6RZGY070806</b>	Versionname:	<b>1.4 TDI 55KW TRENDLINE BMT</b>
First Registrationdate:	<b>25/09/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>80865</b>	Power Kw:	<b>55</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3608</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options	
Radio CD	Luggage cover
Windows electric F	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>No GPS</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
Summer tyres:	<b>175/70/14/84 T Steel</b>			
	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

Assistance equipment			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			2067,86
Bumper R, Scratch(es), LI - Repair and paint (complete)			169,44




Wheel cover R R, Missing, E - Replace	24,00
---------------------------------------	-------



Door F L, Scratch(es), LI - Repair and paint (complete)	254,68
<i>No pictures to display</i>	
Door R R, Scratch(es), LI - Repair and paint (complete)	254,68



Wing R L, Scratch(es), LI - Repair and paint (complete) 246,56



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Scratch(es), LI - Repair and paint (complete) 385,20



Wing R R, Scratch(es), LI - Repair and paint (complete) 246,56



Bonnet, Scratch(es), LI - Repair and paint (complete) 232,06



Door F R, Scratch(es), LI - Repair and paint (complete) 254,68



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display