



TOYOTA GRAND PRIUS+: 1PSP897

Vinnumber:	JTDZS3EU30J009607	Versionname:	1.8 VVT-i Hybrid Lounge
First Registrationdate:	7/09/2016	Fiscalpower:	
Expertise Mileage:	38971	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	3314
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/50/17/92 V LightMetal			
Summer tyres:	Fr.L.	Toyo: 3 mm	Fr.R.	Toyo: 3 mm
	Re.L.	Toyo: 4 mm	Re.R.	Toyo: 4 mm

Assistance equipment



















Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------


Total cost ex VAT	1929,54
-------------------	----------------

Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	---------------



Wing F R, Dent(s) and scratch(es), Le - Replace and paint	0,00
---	-------------

		Bumper F, Crack, Le - Replace and paint	0,00
		Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
		Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00
		Alloy rim F R, Scratch(es), E - Replace	235,20
		Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
		Tyre R L, Tear, E - Replace	132,00
		Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
		Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
		Bumper trim R, Scratch(es), Smart repair	110,64



Interior, Dirty, Cleaning

50,00



Ignition key, Missing, E - Replace

150,00

No pictures to display