



CITROEN DS4: 1FSE181

Vinnumber:	VF7NX9HD8DY592769	Versionname:	DS4 BER e-HDi Business GPS 115PK
First Registrationdate:	8/10/2013	Fiscalpower:	
Expertise Mileage:	124763	Power Kw:	84
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2119
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/95 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1495,43
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)



Certificate Of Conformity, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Protection plate M, Deformed / Strained, E - Replace	74,00



Rearview mirror housing R, Scratch(es), Smart repair	110,64
--	--------



Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Rearview mirror housing L, Scratch(es), Smart repair	110,64
--	--------



GPS disc, Missing, E - Replace	275,00
--------------------------------	--------

