



VOLKSWAGEN Golf: 1EZB423

Vinnumber:	VVWZZZ1KZDM672919	Versionname:	GOLF BRE Trendline BlueMot.DPF 105PK
First Registrationdate:	25/04/2013	Fiscalpower:	
Expertise Mileage:	62869	Power Kw:	77
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3427
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment



Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	693,35
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Roof, Dent(s), Acceptable

0,00

<i>No pictures to display</i>		
Boot carpet, Damaged, E - Replace		100,00
		
Ignition key, Missing, E - Replace		150,00
<i>No pictures to display</i>		
Door F L, Scratch(es), LI - Repair and paint (complete)		318,35
		
Alloy rim F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bodywork, Not original part, Acceptable		0,00
<i>No pictures to display</i>		
Mirror side blinker R, Broken, E - Replace		30,00
