



BMW 2 ACTIVE TOURER: 1KCV462

Vinnumber:	WBA2C11030V342854	Versionname:	2.0 218D (110KW) ACTIVE TOURER
First Registrationdate:	2/04/2015	Fiscalpower:	
Expertise Mileage:	62542	Power Kw:	110
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	4504
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Sun Roof electric	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Hankook: 2 mm	Fr.R.	Hankook: 2 mm
	Re.L.	Hankook: 5 mm	Re.R.	Hankook: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1664,90
-------------------	----------------

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Interior, Dirty, Cleaning

50,00



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Tailgate, Not original part, Acceptable

0,00

No pictures to display

Maintenance, Maintenance, Execute

0,00



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Ignition key, Missing, E - Replace

150,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20

