



MERCEDES A: SF8173

Vinnumber:	WDD1760081V051276	Versionname:	2.1 A 200 CDI AMG LINE
First Registrationdate:	8/07/2015	Fiscalpower:	
Expertise Mileage:	110922	Power Kw:	100
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2326
Number of doors:	5		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/40/18/92 V LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1971,18
Wing R R, Dent(s), LI - Repair and paint (complete)			404,20



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), E - Replace 235,20



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R polished, Scratch(es), E - Replace 235,20



Alloy rim F L polished, Scratch(es), E - Replace 235,20



Seat cover F L, Damaged, Acceptable 0,00



Interior, Smell, Ozone treatment 152,58



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R R polished, Scratch(es), E - Replace

235,20



Door R L, Dent(s), Acceptable

0,00

No pictures to display

Boot cover, Scratch(es), E - Replace

50,00

