



VOLKSWAGEN Golf: 1GRJ609

Vinnumber:	VVWZZZAUZEW353799	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	8/04/2014	Fiscalpower:	
Expertise Mileage:	128440	Power Kw:	77
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1222
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	No Tow bar
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/65/15/88 H Steel				
Summer tyres:	Fr.L.	Other: 7 mm	Fr.R.	Other: 7 mm
	Re.L.	Other: 7 mm	Re.R.	Other: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 1726,77

Luggage space cover, Missing, E - Replace 240,00



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Armrest R M, Damaged, Smart repair

64,32



Rear window, Scratch(es), E - Replace

370,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wheel cover F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

310,50



Door R L, Scratch(es), Acceptable

0,00

No pictures to display