



VOLKSWAGEN Golf: 1HVZ987

Vinnumber:	WVWZZZAUZFP031782	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	17/10/2014	Fiscalpower:	
Expertise Mileage:	158006	Power Kw:	77
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1414
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/14/91 T Steel			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment


Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			730,08
Door R R, Dent(s) and scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)			290,08



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 0,00




Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



Bumper R, Bad repair, Paint 0,00



Wing R L, Bad repair, LI - Repair and paint (complete) 0,00



Seat cover F L, Damaged, E - Replace 360,00



Wing F L, Repaired, Acceptable 0,00

No pictures to display

Door R L, Bad repair, Paint 0,00



Interior, Dirty, Cleaning 50,00



