


SKODA FABIA COMBI: HD5307

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------------------|
| Vinnumber: | TMBJK25J5F3021705 | Versionname: | 1.2 CR TDI 55KW 99G AMBITION |
| First Registrationdate: | 29/04/2015 | Fiscalpower: | |
| Expertise Mileage: | 87736 | Power Kw: | 55 |
| Bodytype: | Break | Body color: | White |
| Gearbox: | MAN 5 VIT | Paint type: | Opaque |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2606 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|-------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | Type of Tow bar |
| Radio multimedia | No Tow bar |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | No GPS |
| Type of Lining | Lining fabrics |
| Type of climate control | Manual climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|----------------------|-------|----------------------|
| | 195/55/15/85 H Steel | | | |
| Summer tyres: | Fr.L. | Hankook: 4 mm | Fr.R. | Hankook: 4 mm |
| | Re.L. | Hankook: 4 mm | Re.R. | Hankook: 4 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|-------------------|---------------|
| Total cost ex VAT | 150,00 |
|-------------------|---------------|

| | |
|-----------------------------------|-------------|
| Bonnet, Stone chip(s), Acceptable | 0,00 |
|-----------------------------------|-------------|

No pictures to display

| | |
|---|-------------|
| Bodywork, Not original part, Acceptable | 0,00 |
|---|-------------|

No pictures to display

| | |
|-----------------------------------|-------------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|-------------|

No pictures to display

| | |
|-----------------------------------|---------------|
| Ignition key, Missing, F. Replace | 150,00 |
|-----------------------------------|---------------|

| | |
|------------------------------------|--------|
| Ignition key, missing, € - replace | 150,00 |
| <i>No pictures to display</i> | |
| Windscreen, Repaired, Acceptable | 0,00 |
| <i>No pictures to display</i> | |