



SKODA Octavia: 1GUH294

Vinnumber:	TMBJG7NE4E0211691	Versionname:	OCTAVIA COMBI Ambition 105PK
First Registrationdate:	2/05/2014	Fiscalpower:	
Expertise Mileage:	124044	Power Kw:	77
Bodytype:		Body color:	Red
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	3000 KM	Parking lot:	4406
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Sun Roof electric	
GPS storage	SD	Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V Steel				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	897,10
Wheel cover R L, Scratch(es), E - Replace	30,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Maintenance, Maintenance, P - Check

0,00



Sill outer R, Dent(s), LI - Repair and paint (complete)

358,50



Door F R, Dent(s), Acceptable

0,00

No pictures to display

Ceiling, Stain, Cleaning

25,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Mirror side blinker R, Broken, E - Replace

30,00



Wheel cover R R, Missing, E - Replace

30,00



Bonnet, Bad repair, LI - Repair and paint (complete)

0,00



Door R R, Dent(s), Acceptable

0,00

No pictures to display