



BMW 3 GRAN TURISMO: 1JSB974

Vinnumber:	WBA3Y11050GD87193	Versionname:	2.0 318D (100KW) GRAN TURISMO
First Registrationdate:	11/02/2015	Fiscalpower:	
Expertise Mileage:	161754	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1426
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar removable
Seats F heated	
Type of headlighting	Headlighting Xenon
Type of Lining	Lining semi-leather
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/18/95 W LightMetal				
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 3 mm	Re.R.	Pirelli: 3 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	809,76
-------------------	---------------

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------





Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00




Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Wing F R, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Dent(s), Acceptable

0,00



Bumper moulding F R, Broken, E - Replace

14,40



Bumper F, Dent(s) and scratch(es), It - Spot repair

115,56



Bumper moulding R, Scratch(es), Tu - Touch up

25,00

