



VOLKSWAGEN CADDY: SF8398

| | | | |
|------------------------------------|---------------------------------|--------------|---|
| Vinnumber: | WV1ZZZ2KZFX137730 | Versionname: | CADDY VAN B/F Base 75kw Spec.LUXEMBOUR |
| First Registrationdate: | 13/05/2015 | Fiscalpower: | |
| Expertise Mileage: | 103222 | Power Kw: | 75 |
| Bodytype: | Transporter | Body color: | White |
| Gearbox: | MAN 5 VIT | Paint type: | Opaque |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3531 |
| Number of doors: | 5 | | |
| Number of seats: | 2 | | |
| Number head rests: | 2 | | |
| Rims summer: | Steel | | |
| Category: | Light Commercial Vehicle | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|-------------------------|-------------------------------|----------------------|-------------------|
| Radio CD | | Rear parking sensors | |
| Windows electric F | | Type of Tow bar | No Tow bar |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | No GPS | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Manual climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------|-------|----------------------|-------|----------------------|
| 195/65/15/91 T Steel | | | | |
| Summer tyres: | Fr.L. | Hankook: 4 mm | Fr.R. | Hankook: 4 mm |
| | Re.L. | Hankook: 4 mm | Re.R. | Hankook: 4 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

Total cost ex VAT 724,80

Bumper R, Scratch(es), E - Replace 329,40





Windscreen, Crack, E - Replace 395,40



Bodywork, Glue residues, Acceptable 0,00

