



BMW X5: 1GKL896

Vinnumber:	WBAKR010300M64782	Versionname:	
First Registrationdate:	21/05/2015	Fiscalpower:	
Expertise Mileage:	123671	Power Kw:	225
Bodytype:	SUV	Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3126
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

255/50/19/107 V LightMetal				
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	2405,58
Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)	362,02



Door R L, Scratch(es), LI - Repair and paint (complete)

382,02



Armrest L, Worn, Acceptable

0,00

No pictures to display

Spoiler R, Scratch(es), Acceptable

0,00

No pictures to display


Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

115,56



Windscreen, Crack, E - Replace

560,64



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Sill outer R, Scratch(es), Acceptable

0,00

Door F L, Scratch(es), LI - Repair and paint (complete) 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete) 382,02



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

