



PEUGEOT 5008: 1JSB715

Vinnumber:	VF30E9HD8FS025042	Versionname:	1.6 HDI 84KW ALLURE
First Registrationdate:	11/02/2015	Fiscalpower:	
Expertise Mileage:	110541	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4733
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Panoramic roof	
TV/DVD screen R		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/50/17/95 Y LightMetal				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1024,96
--------------------------	----------------

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
--	---------------



Wing R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Worn, Acceptable	0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing F R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Ignition key, Worn, E - Replace	150,00



Door R L, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner F R, Dent(s), LI - Repair and paint (complete)	115,56



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Tailgate, Dent(s), PDR - Paintless dent repair

82,80



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display