



BMW 1 HATCH: 1LJK851

Vinnumber:	WBA1V910105B19784	Versionname:	1.5 116D EFFICIENTDYNAMICS EDIT. (85KW)
First Registrationdate:	5/10/2015	Fiscalpower:	
Expertise Mileage:	118503	Power Kw:	85
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4827
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal			
Summer tyres:	Fr.L. Michelin: 4 mm	Fr.R. Michelin: 4 mm	
	Re.L. Goodyear: 4 mm	Re.R. Goodyear: 4 mm	

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2379,78
Door F L, Scratch(es), LI - Repair and paint (complete)	318,35



Alloy rim F L, Scratch(es), I - Repair

100,00



Wing F R, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Bonnet, Dent(s), LI - Repair and paint (complete)

290,08



Roof, Dent(s), PDR - Paintless dent repair

63,00



Sill trim L, Scratch(es), LI - Repair and paint (complete)

255,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim R L, Scratch(es), LI - Repair

100,00

Alloy rim R L, Scratch(es), I - Repair

100,00



Bumper F, Hole, Le - Replace and paint

735,00



Alloy rim F R, Scratch(es), I - Repair

100,00



Alloy rim R R, Scratch(es), I - Repair

100,00

