



VOLKSWAGEN Caddy: 1GVM205

Vinnnumber:	WV2ZZZ2KZEX140701	Versionname:	CADDY MAXI LIFE 2PLC Comfortl. BM 102PK
First Registrationdate:	12/05/2014	Fiscalpower:	
Expertise Mileage:	156529	Power Kw:	75
Bodytype:	MPV	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2828
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/94 H LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1966,55
Internal Boot Lining R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Bonnet, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Floor covering F L, Tear, E - Replace	237,00




Roof, Chemical polution, LI - Repair and paint (complete)	361,13
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	158,85
---	--------



Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Dent(s), PDR - Paintless dent repair	63,00





Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

362,02




Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Windscreen, Stone chip(s), E - Replace

395,40



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Outer door handle F R, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s), PDR - Paintless dent repair

63,00

