



VOLKSWAGEN Golf: 1EZG365

Vinnumber:	WVWZZZAUZDW131857	Versionname:	GOLF BER Trendline DSG 105PK Aut.
First Registrationdate:	26/04/2013	Fiscalpower:	
Expertise Mileage:	121403	Power Kw:	77
Bodytype:	Hatchback	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3101
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Type of Tow bar	No Tow bar
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	195/65/15/91 V Steel			
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Number of charging cables (normal)	0	Jack	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1617,18
-------------------	----------------

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	---------------



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), Acceptable 0,00



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 220,18



Seat cover F L, Stain, Cleaning 25,00



Floor covering F L, Hole, E - Replace 252,00



Seat cover R, Stain, Cleaning 25,00



Seat cover F R, Stain, Cleaning

25,00



Wheel cover F L, Missing, E - Replace

30,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



