


**LU Volkswagen Golf: YS8443**

Vinnumber:	<b>WVWZZZAUZGP109838</b>	Versionname:	<b>1.6 TDI 81KW HIGHLINE</b>
First Registrationdate:	<b>13/06/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>136435</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:		Oil level:	<b>NOT OK</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>NOT OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>SD</b>	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting LED</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining semi-artificial leather</b>	
Type of climate control	<b>Autom climate control</b>	
Sport seats		

**Limited Technical Inspection**

Tires wear profile	<b>OK</b>	Battery functioning	<b>Yes</b>
Idle position	<b>NOT OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>NOT OK</b>	Lighting	<b>OK</b>
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>225/45/17/92 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>1074,70</b>
Wing F R, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Interior, Dirty, Cleaning	<b>0,00</b>



Door F L, Dent(s), PDR - Paintless dent repair 63,00



Internal Boot Lining R, Broken, E - Replace 69,00



Windscreen, Stone chip(s), E - Replace 487,20



Sill outer R, Dent(s), LI - Repair and paint (complete) 310,50



Rear bulkhead lining, Missing, E - Replace 50,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

