



PEUGEOT 308: 1HXJ375

Vinnumber:	VF3LCBHXHES226544	Versionname:	308 SW BlueHDi Active STT 116PK
First Registrationdate:	21/10/2014	Fiscalpower:	
Expertise Mileage:	154168	Power Kw:	85
Bodytype:	Break	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1412
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 1007,44

Door F L, Dent(s), PDR - Paintless dent repair 63,00




Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)



Bumper grille, Deformed / Strained, E - Replace 32,40



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Scratch(es), 67 - Polish 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Luggage space cover, Missing, E - Replace 240,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper grille F L, Deformed / Strained, E - Replace 32,40



Bumper grille F R, Deformed / Strained, E - Replace

32,40

