



VOLKSWAGEN TOURAN: 1NHZ665

Vinnumber:	WVGZZZ1TZGW557382	Versionname:	1.6 TDI SCR 81KW BMT TRENDLINE
First Registrationdate:	1/03/2016	Fiscalpower:	
Expertise Mileage:	148737	Power Kw:	81
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3510
Maintenance:	BINNEN 12500 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 W Steel				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 707,55

Interior, Dirty, Cleaning 100,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wheel cover F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s), PDR - Paintless dent repair

63,00



Bonnet, Chemical polution, 67 - Polish

0,00



Wheel cover F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F R, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair

0,00



Rocker panel inner R R, Dent(s), LI - Repair and paint (partial)

115,56



Trunk lid covering R, Scratch(es), Smart repair	110,64
---	--------



Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display