



AUDI A5 SPORTBACK: 1KXV701

Vinnumber:	WAUZZZ8T0GA006933	Versionname:	2.0 TDI 110KW
First Registrationdate:	28/07/2015	Fiscalpower:	
Expertise Mileage:	87821	Power Kw:	110
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3510
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

245/40/18/97 Y LightMetal				
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Emergency spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	2813,12
Bonnet, Chemical polution, LI - Repair and paint (complete)	348,09



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Scratch(es), LI - Repair and paint (complete)

382,02



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Dent(s), Acceptable

0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete)

264,21





Windscreen, Stone chip(s), E - Replace

560,64



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display