


FORD Focus: 1JNX596

Vinnumber:	WF0KXXGCBKEB71508	Versionname:	FOCUS BER ECONetic Trend 88g 105PK
First Registrationdate:	28/01/2015	Fiscalpower:	
Expertise Mileage:	175426	Power Kw:	77
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	GEEN MELDING	Parking lot:	2601
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover
GPS storage	SD	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 W Steel				
Summer tyres:	Fr.L.	Vredestein: 6 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1418,36
Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Missing, E - Replace	30,00



Boot cover, Missing, E - Replace 50,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Internal Boot Lining R, Scratch(es), Smart repair 110,64



Wheel cover F L, Scratch(es), E - Replace 30,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Ceiling, Burned, Smart repair 64,32



Mirror side blinker R, Broken, E - Replace 30,00



Seat cover F L, Hole, E - Replace 360,00



Rearview mirror R complete, Broken, E - Replace

168,00



Bumper trim R, Dent(s) and scratch(es), Smart repair

110,64



Instruction book, Missing, E - Replace

0,00



Trunk lid covering R, Scratch(es), Smart repair

110,64



Wheel cover R R, Scratch(es), E - Replace

30,00



Wing R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Floor covering F L, Burned, Smart repair

112,32

