



VOLKSWAGEN Golf: 1HJV570

Vinnumber:	WVWZZZAUZEW261542	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	5/08/2014	Fiscalpower:	
Expertise Mileage:	136610	Power Kw:	77
Bodytype:	Hatchback	Body color:	Brown
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1723
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


195/65/15/91 H Steel				
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 673,78

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 220,18



Roof, Dent(s), Acceptable 0,00

No pictures to display

Roof, Chemical polution, 67 - Polish 0,00

No pictures to display

Wheel cover F L, Missing, E - Replace 30,00




Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Scratch(es), 67 - Polish 0,00

No pictures to display

Bonnet, Bad repair, Acceptable 0,00



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Windscreen, Repaired, Acceptable 0,00

