



LAND ROVER DISCOVERY SPORT: XH6441

Vinnumber:	SALCA2BC5FH509436	Versionname:	2.0 TD4 110KW HSE 4WD AUTO
First Registrationdate:	6/08/2015	Fiscalpower:	
Expertise Mileage:	64219	Power Kw:	110
Bodytype:	SUV	Body color:	Green
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3706
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	235/55/19/105 V LightMetal			
	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 7 mm	Re.R.	Dunlop: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2548,95
Bumper corner R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Door R L, Dent(s) and scratch(es), Acceptable 0,00
No pictures to display

Bumper R, Scratch(es), Smart repair 110,64



Rearview mirror housing R, Scratch(es), Acceptable 0,00




Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Dent(s) and scratch(es), Acceptable 0,00
No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 348,09



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 430,02



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door trim R R, Deformed / Strained, E - Replace

132,00





Ignition key, Missing, E - Replace 150,00

No pictures to display

Wing R L, Bad repair, Acceptable 0,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper corner R R, Scratch(es), Acceptable 0,00

No pictures to display