


BMW 2 ACTIVE TOURER: 1KCL141

Vinnumber:	WBA2B31060V381002	Versionname:	1.5 216D ACTIVE TOURER
First Registrationdate:	1/04/2015	Fiscalpower:	
Expertise Mileage:	112440	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	SERVICE IN 14000KM 3 2020	Parking lot:	4120
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1298,05
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Instruction book, Missing, E - Replace	0,00



Roof, Chemical pollution, LI - Repair and paint (complete)	481,50
--	--------



Door R L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Tailgate, Not original part, Acceptable	0,00
---	------

No pictures to display

Door F R, Bad repair, LI - Repair and paint (complete)	318,35
--	--------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing R L, Bad repair, LI - Repair and paint (complete)	308,20
--	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

