



BMW 2 GRAN TOURER: 1LBY949

Vinnumber:	WBA2E310405C00747	Versionname:	1.5 216D GRAN TOURER
First Registrationdate:	14/08/2015	Fiscalpower:	
Expertise Mileage:	172703	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	468
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	NOT OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Fulda: 5 mm	Fr.R.	Fulda: 5 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2061,16
-------------------	----------------

Door panel R L, Tear, E - Replace	114,00
-----------------------------------	---------------





Interior, Worn, Forfeit



Tailgate, Scratch(es), Acceptable



Door panel R R, Scratch(es), Smart repair



Ignition key, Worn, Acceptable



Alloy rim R R, Scratch(es), Acceptable



Backrest cover R M, Worn, E - Replace



Luggage space cover, Missing, E - Replace



Ceiling, Stain, Cleaning

25,00



Backrest cover F L, Scratch(es), Smart repair

64,32



Rearlight L, Broken, E - Replace

114,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Backrest cover F R, Scratch(es), Smart repair

64,32



Interior, Dirty, Cleaning

100,00





Trunk lid covering R, Scratch(es), Smart repair

110,64



Door panel F L, Tear, E - Replace

114,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Rear wiper arm, Missing, E - Replace

15,00

