


RENAULT CLIO GRANDTOUR: 1NNU771

Vinnumber:	VF17RBF0A54617567	Versionname:	1.5 ENERGY DCI 75 EXPRESSION
First Registrationdate:	29/03/2016	Fiscalpower:	
Expertise Mileage:	55203	Power Kw:	55
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2809
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Luggage cover	
Cruise Control	Type of Tow bar	No Tow bar
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 T Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1184,18
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel R L, Scratch(es), E - Replace	96,00



Roof pillar L, Dent(s), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44




Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,68



Bonnet, Chemical polution, LI - Repair and paint (complete) 232,06



Wheel cover F L, Scratch(es), E - Replace 24,00



Door trim F R, Dent(s), E - Replace 96,00



Seat cover F L, Hole, E - Replace 312,00

