



VOLKSWAGEN SHARAN: 1LDJ098

Vinnumber:	VVWZZZ7N2GV208690	Versionname:	2.0 CR TDI 85KW TRENDLINE BMT
First Registrationdate:	27/08/2015	Fiscalpower:	
Expertise Mileage:	141332	Power Kw:	85
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1333
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 W Steel				
Summer tyres:	Fr.L.	Kleber: 6 mm	Fr.R.	Kleber: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Repair kit	No	Compressor	No
------------	-----------	------------	-----------

Total cost ex VAT	1595,40
-------------------	----------------

Electricity circuit, Not functioning (well), P - Check	0,00
--------------------------------------------------------	-------------




Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Seat cover R R, Scratch(es), Smart repair

64,32



Wheel cover F R, Scratch(es), E - Replace

36,00



Foglight R, Broken, E - Replace

156,00



Door F L, Dent(s), Acceptable

0,00

No pictures to display

Tyre repair kit, Missing, E - Replace

252,64



Windscreen, Stone chip(s), E - Replace

560,64



Wheel cover R R, Scratch(es), E - Replace

36,00



Door R L, Repaired, No repair

0,00



Reflector, Broken, E - Replace

25,00



Trunk lid covering R, Scratch(es), Smart repair

110,64



Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Interior, Dirty, Cleaning

100,00



Bumper F R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), Acceptable

0,00

No pictures to display