



**TOYOTA PRIUS: 1PSE150**

Vinnumber:	<b>JTDKB3FU403530677</b>	Versionname:	<b>1.8 VVT-i Hybrid Lounge</b>
First Registrationdate:	<b>5/09/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>41766</b>	Power Kw:	<b>90</b>
Bodytype:		Body color:	<b>Red</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level:	<b>OK</b>
Maintenance:	<b>CONTROLEREN</b>	Parking lot:	<b>2408</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	
Adaptive cruise control		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/45/17/87 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Yokohama: 6 mm</b>	Fr.R.	<b>Yokohama: 6 mm</b>
	Re.L.	<b>Yokohama: 6 mm</b>	Re.R.	<b>Yokohama: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
		Jack	<b>Yes</b>

Total cost ex VAT	<b>960,60</b>
Bonnet, Scratch(es), Acceptable	<b>0,00</b>



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Protection plate M, Tear, E - Replace

228,60



Alloy rim R R, Scratch(es), E - Replace

235,20



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Maintenance, Maintenance, P - Check

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

