



**BMW 5 TOURING: 1KPF265**

Vinnumber:	<b>WBA5L11040D786120</b>	Versionname:	<b>2.0 518D (100KW) TOURING</b>
First Registrationdate:	<b>9/06/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>189059</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2331</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Central consol F
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Xenon</b>
Type of Lining	<b>Lining artificial leather</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/55/17/101 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Vredestein: 6 mm</b>	Fr.R.	<b>Vredestein: 6 mm</b>
	Re.L.	<b>Firestone: 7 mm</b>	Re.R.	<b>Firestone: 7 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>Yes</b>
------------	-----------	------------	------------

Total cost ex VAT 1059,20

Wing R L, Scratch(es), Acceptable 0,00



Seat cover F L, Worn, P - Check 0,00



Alloy rim F L, Scratch(es), Acceptable

0,00



Alloy rim R R, Scratch(es), Acceptable

0,00



Roof pillar L, Dent(s), PDR - Paintless dent repair

63,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Tyre repair kit, Missing, E - Replace

252,64



Backrest cover F L, Worn, P - Check

0,00



Ignition key, Missing, E - Replace

150,00



Alloy rim F R, Scratch(es), I - Repair

100,00




GPS, Not functioning (well), P - Check

0,00



Roof, Dent(s), Acceptable

0,00



Reflector, Broken, E - Replace

60,80



Tyre F R, Tear, E - Replace

153,60



Rocker panel inner F R, Missing, Forfeit

25,00



Alloy rim R L, Scratch(es), Acceptable

0,00

