



FORD FOCUS CLIPPER: 1LKS493

Vinnumber:	WF06XXGCC6FK41376	Versionname:	1.5 TDCI 88KW S/S BUSINESS EDITION+
First Registrationdate:	14/10/2015	Fiscalpower:	
Expertise Mileage:	124675	Power Kw:	88
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3405
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	Tow bar fixed
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	409,80
-------------------	---------------

Alloy rim F R, Scratch(es), Acceptable	0,00
----------------------------------------	-------------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---------------------------------------------------------	---------------



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door panel R L, Scratch(es), E - Replace 114,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), E - Replace 84,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display