



**MERCEDES CLA SHOOTING BRAKE: 1LJU698**

Vinnumber:	<b>WDD1179081N279307</b>	Versionname:	<b>2.1 CLA 200 CDI SHOOTING BRAKE</b>
First Registrationdate:	<b>7/10/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>149462</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3232</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining semi-artificial leather</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

Summer tyres:	<b>205/55/16/91 V LightMetal</b>			
	Fr.L.	<b>Vredestein: 5 mm</b>	Fr.R.	<b>Vredestein: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>2010,15</b>
-------------------	----------------

Seat cover R, Stain, Cleaning	<b>25,00</b>
-------------------------------	--------------



Door F R, Repaired, Acceptable	<b>0,00</b>
--------------------------------	-------------



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

366,35



Backrest cover F L, Tear, E - Replace

360,00



Interior, Smell, Ozone treatment

152,58



Internal Boot Lining L, Tear, E - Replace

156,18



Seat cover F R, Stain, Cleaning

25,00



Bumper F, Repaired, Acceptable

0,00



Internal Boot Lining R, Tear, E - Replace

156,18



Alloy rim F R, Scratch(es), I - Repair

100,00





Seat cover F L, Burned, E - Replace

360,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Repaired, Acceptable

0,00



Mats, Burned, E - Replace

213,86



Maintenance, Maintenance, P - Check

0,00

