



PEUGEOT Boxer 335: 1BVN345			
Vinnumber:	VF3YCTMGC12059661	Versionname:	BOXER 335 PL2C LWB L3 FAP 130PK
First Registrationdate:	14/09/2011	Fiscalpower:	
Expertise Mileage:	63966	Power Kw:	96
Bodytype:	Transporter	Body color	White
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	LCV15
Number of doors	4		
Number of seats	7		
Number head rests	7		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		

Options			
Radio CD		Type of Tow bar	Tow bar fixed
Windows electric F			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	215/70/15/109 S Steel			
	Fr.L.	Dunlop: 7 mm	Fr.R.	Dunlop: 7 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment		Jack	Yes
Total cost ex VAT			4307,11
Seat cover F L, Damaged, E - Replace			300,00



Door panel R L, Broken, E - Replace	91,50
-------------------------------------	-------



Seat cover F R, Damaged, E - Replace

300,00



Interior, Dirty, Cleaning

20,00



Wing R L, Dent(s), It - Spot repair

115,56



Wing R R 3P, Rust, It - Spot repair

115,56



Sill outer L, Scratch(es), LI - Repair and paint (complete)

232,88



Wing F L, Bad repair, LI - Repair and paint (complete)

165,13



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Ignition key, Missing, E - Replace

150,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Window F R door, Not functioning (well), I - Repair

48,00



Roof, Rust, LI - Repair and paint (complete)

361,13



Tailgate handle, Broken, E - Replace

51,00



Door moulding Lower F L, Missing, E - Replace

91,50



Sill outer R, Scratch(es), LI - Repair and paint (complete)


232,88



Wing R R, Dent(s), It - Spot repair

115,56





Inner door handle R L, Broken, E - Replace

33,00



Bumper F, Scratch(es), E - Replace

398,40



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

165,13



Protection plate M, Tear, E - Replace

74,00



Seat cover R L, Tear, E - Replace

300,00



Tailgate handle, Broken, E - Replace

51,00



Window F L door, Not functioning (well), I - Repair

48,00

No pictures to display

Tailgate, Dent(s), It - Spot repair

115,56



Rearview mirror R complete, Broken, E - Replace

138,00



Inner door handle R R, Broken, E - Replace

33,00



Bonnet, Dent(s), PDR - Paintless dent repair

82,80

