



PEUGEOT BOXER: 1PJV097

Vinnumber:	VF3YDUMAU12B69012	Versionname:	2.2 HDI 150 PRO 435 L3
First Registrationdate:	18/07/2016	Fiscalpower:	
Expertise Mileage:	234069	Power Kw:	110
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV03
Number of doors:	4		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Type of Tow bar	No Tow bar
GPS storage			
Windows electric F			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

255/75/16/114 C Steel				
Winter tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 9 mm	Re.R.	Continental: 9 mm

Assistance equipment

Spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1124,53
Central pillar L, Dent(s) and scratch(es), It - Spot repair	115,56



Door F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Roof, Scratch(es), Acceptable 0,00



Sidewall RR (LCV), Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



A-pillar right, Scratch(es), Acceptable 0,00

No pictures to display

Sidewall RL (LCV), Scratch(es), LI - Repair and paint (complete) 231,15



Door frame F L, Scratch(es), It - Spot repair 115,56





Tailgate, Scratch(es), Acceptable

0,00



A-Pillar left, Scratch(es), LI - Repair and paint (complete)

124,23



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Central pillar R, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

232,88



Sill trim F R, Broken, E - Replace

74,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display