



TOYOTA GRAND PRIUS+: 1SPP257

Vinnumber:	JTDZS3EU70J018259	Versionname:	1.8 VVT-i Hybrid Active
First Registrationdate:	21/06/2017	Fiscalpower:	
Expertise Mileage:	47157	Power Kw:	100
Bodytype:		Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Hybrid Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	1422
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V Steel				
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			2933,37
Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)			115,56



Front end, Scratch(es), It - Spot repair

115,56



Wing F R, Dent(s), PDR - Paintless dent repair

63,00



Internal Boot Lining L, Scratch(es), Smart repair

110,64



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

358,50



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80





Windscreen, Tear, E - Replace

487,20



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Internal Boot Lining R, Scratch(es), Smart repair

110,64



Bumper R, Deformed / Strained, Le - Replace and paint

651,00




A-pillar right, Scratch(es), Acceptable

0,00

No pictures to display

Interior, Dirty, Cleaning

100,00



Spoiler R, Scratch(es), It - Spot repair

115,56





Wheel cover F R, Scratch(es), E - Replace

30,00



Wheel cover R R, Scratch(es), E - Replace

30,00



Wing R L, Dent(s), Acceptable

0,00

No pictures to display