



PEUGEOT 508: 1HYP452

| | | | |
|------------------------------------|--------------------------|--------------|---------------------------------------------------|
| Vinnumber: | VF38E9HD8EL040921 | Versionname: | 508 SW e-HDi Active S&S ETG 115PK Aut. |
| First Registrationdate: | 30/10/2014 | Fiscalpower: | |
| Expertise Mileage: | 148388 | Power Kw: | 84 |
| Bodytype: | | Body color: | Brown |
| Gearbox: | Automatic | Paint type: | Metallic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3509 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|--------------------------|
| Radio CD | | Seats electric F L | |
| GPS storage | | Seats electric F R | |
| GPS storage | HD | Panoramic roof | |
| Windows electric F | | Central consol F | |
| Windows electric R | | Luggage cover | |
| Cruise Control | | Front parking sensors | |
| Steering wheel multifunctional | | Rear parking sensors | |
| Seats F heated | | Type of Tow bar | Tow bar removable |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| 215/55/17/98 V LightMetal | | | | |
| Winter tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|-----------------------------------------------------------------------|---------------|
| Total cost ex VAT | 740,84 |
| Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |



| | |
|----------------------------------------|--------|
| Bumper R, Hole, Le - Replace and paint | 535,20 |
|----------------------------------------|--------|



| | |
|-------------------------------------------------------|------|
| Alloy rim R R polished, Not original part, Acceptable | 0,00 |
|-------------------------------------------------------|------|

No pictures to display

| | |
|----------------------------------|------|
| Seat cover F L, Worn, Acceptable | 0,00 |
|----------------------------------|------|

No pictures to display

| | |
|---------------------------------------|------|
| Windscreen, Stone chip(s), Acceptable | 0,00 |
|---------------------------------------|------|

No pictures to display

| | |
|-------------------------------|------|
| Door R L, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

| | |
|-------------------------------------------------|------|
| Alloy rim R L polished, Scratch(es), Acceptable | 0,00 |
|-------------------------------------------------|------|

No pictures to display

| | |
|-------------------------------------------|------|
| Central pillar L, Scratch(es), Acceptable | 0,00 |
|-------------------------------------------|------|

No pictures to display

| | |
|-------------------------------------------------|--------|
| Trunk lid covering R, Scratch(es), Smart repair | 110,64 |
|-------------------------------------------------|--------|

