



BMW 2 ACTIVE TOURER: 1LRT902

Vinnumber:	WBA2B31080V691779	Versionname:	1.5 216D ACTIVE TOURER
First Registrationdate:	17/11/2015	Fiscalpower:	
Expertise Mileage:	63782	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1324
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1652,75
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Dashboard, Glue residues, Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Number plate cover F, Broken, E - Replace 20,40



Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35





Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R L, Scratch(es), 67 - Polish	0,00
------------------------------------	------

No pictures to display

Windscreen, Stone chip(s), E - Replace	487,20
--	--------

