



VOLKSWAGEN TIGUAN: 1PUF362

Vinnumber:	WVGZZZ5NZHW824881	Versionname:	2.0 TDI BMT SCR 110KW DSG7 COMFORTLINE
First Registrationdate:	20/09/2016	Fiscalpower:	
Expertise Mileage:	157016	Power Kw:	110
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3704
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/65/17/99 V LightMetal				
Summer tyres:	Fr.L.	Toyo: 5 mm	Fr.R.	Toyo: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		






Total cost ex VAT 2087,73


Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Rear window, Scratch(es), Acceptable	0,00
	
Alloy rim F R polished, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F R, Scratch(es), E - Replace	19,20
	
Registration Document, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
	
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	366,35
	
Rocker panel inner F R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper cover R M, Deformed / Strained, E - Replace	171,00
	
Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35



Alloy rim F L polished, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Bumper F L, Missing, E - Replace 19,20



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 301,68





Windscreen, Stone chip(s), Acceptable

0,00

