



BMW 2 ACTIVE TOURER: 1JXU545

Vinnumber:	WBA2B31070V380747	Versionname:	1.5 216D ACTIVE TOURER
First Registrationdate:	16/03/2015	Fiscalpower:	
Expertise Mileage:	114630	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Maintenance:	BINNEN 23000KM	Parking lot:	3833
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric
GPS storage	HD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Head-up Display		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	4349,67
-------------------	----------------

Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
---	---------------



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door F L, Dent(s) and scratch(es), Le - Replace and paint

1082,52



Door R R, Dent(s) and scratch(es), Le - Replace and paint

946,92



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Luggage space cover, Missing, E - Replace

240,00



Wing F L, Dent(s) and scratch(es), Le - Replace and paint

530,02



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

