



AUDI A3 SPORTBACK: 1LKL928

Vinnumber:	WAUZZZ8V7FA173421	Versionname:	1.6 TDI 81KW AMBITION
First Registrationdate:	13/10/2015	Fiscalpower:	
Expertise Mileage:	87924	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4803
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	No	Compressor	No
------------	-----------	------------	-----------

Total cost ex VAT	957,65
-------------------	---------------

Tyre repair kit, Missing, E - Replace	210,53
---------------------------------------	---------------



Door F R, Dent(s), PDR - Paintless dent repair 63,00



Boot cover, Broken, E - Replace 50,00



Bonnet, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper corner R L, Scratch(es), It - Spot repair 115,56



Bumper F R, Scratch(es), It - Spot repair 115,56



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Ignition key, Missing, E - Replace 150,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display