



TOYOTA AURIS TOURING SPORTS: 1LXL384

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------------------|
| Vinnumber: | SB1Z53JE70E213063 | Versionname: | 1.8 HYBRID LOUNGE CVT AUTO |
| First Registrationdate: | 24/12/2015 | Fiscalpower: | |
| Expertise Mileage: | 54732 | Power Kw: | 100 |
| Bodytype: | Break | Body color: | Brown |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Hybrid Petrol | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2323 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|---------------------------------------|
| Windows electric F | Central consol F |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | Type of Tow bar |
| Radio multimedia | No Tow bar |
| Type of headlighting | Headlighting Xenon |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining semi-artificial leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|---------------------|-------|---------------------|
| 225/45/17/91 W LightMetal | | | | |
| Summer tyres: | Fr.L. | Dunlop: 4 mm | Fr.R. | Dunlop: 4 mm |
| | Re.L. | Dunlop: 4 mm | Re.R. | Dunlop: 4 mm |

Assistance equipment

| | | | |
|--|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

Total cost ex VAT 523,99

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



| | |
|---|--------|
| Trunk lid covering R, Scratch(es), Smart repair | 110,64 |
|---|--------|

No pictures to display

| | |
|-----------------------------------|------|
| Door R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|--|-------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|

