



**PEUGEOT Boxer 330: 1CNA766**

Vinnumber:	<b>VF3Y8TMFA12141845</b>	Versionname:	<b>BOXER 333 B/F L1H2 FAP 130PK</b>
First Registrationdate:	<b>9/01/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>203835</b>	Power Kw:	<b>96</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>LCV03</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/70/15/92 H Steel</b>				
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>1501,00</b>
-------------------	----------------

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	<b>238,76</b>
---	---------------



Bumper F, Dent(s) and scratch(es), Smart repair	<b>110,64</b>
---	---------------



Wing F R, Dent(s), LI - Repair and paint (complete) 165,13



Roof pillar L, Deformed / Strained, Forfeit 62,00



Internal Boot Lining L, Hole, E - Replace 15,00



Internal Boot Lining R, Hole, E - Replace 15,00



Rocker panel inner F L, Scratch(es), Forfeit 115,56



Ignition key, Missing, E - Replace 150,00

No pictures to display  
Door seal F L, Deformed / Strained, E - Replace 46,50



Rearview mirror housing L, Scratch(es), Smart repair 110,64



Bumper R, Scratch(es), Smart repair 110,64





Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Roof, Dent(s), LI - Repair and paint (complete)	361,13
---	--------

