



PEUGEOT Boxer 335: 1CNA702

Vinnumber:	VF3YCTMFB12139850	Versionname:	BOXER 335 B/F MWB HR L2H2 FAP 130PK
First Registrationdate:	9/01/2012	Fiscalpower:	
Expertise Mileage:	99743	Power Kw:	96
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	LCV11
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/70/15/92 H Steel				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 1542,87

Trunk door R L, Dent(s), Acceptable 0,00

No pictures to display

Sliding door panel R, Hole, E - Replace 52,00



Roof, Dent(s) and scratch(es), LI - Repair and paint (complete)

361,13



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Internal Boot Lining R, Hole, E - Replace 42,00



Door F R, Scratch(es), LI - Repair and paint (complete) 238,76



Wing F R, Scratch(es), LI - Repair and paint (complete) 165,13



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Dent(s), Acceptable 0,00

No pictures to display

Door seal F L, Broken, E - Replace 46,50



Bumper R, Scratch(es), Smart repair 110,64



Rearview mirror R complete, Broken, E - Replace 138,00



Internal Boot Lining L, Hole, E - Replace 42,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 231,15



Rocker panel inner F L, Dent(s), LI - Repair and paint (complete)

115,56

