



**OPEL COMBO: 1RDV628**

Vinnumber:	<b>W0L6ZZU1AH9606302</b>	Versionname:	<b>1.3 CDTi 70KW 2.0T L1H1</b>
First Registrationdate:	<b>25/11/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>59806</b>	Power Kw:	<b>70</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4513</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>2</b>		
Number head rests:	<b>2</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	
Windows electric F	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>185/65/15/92 H Steel</b>			
Summer tyres:	Fr.L.	<b>Pirelli: 4 mm</b>	Fr.R.	<b>Pirelli: 4 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>No</b>	Jack	<b>Yes</b>
-------------	-----------	------	------------

Total cost ex VAT	<b>1086,72</b>
-------------------	----------------

Bumper R, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

*No pictures to display*

Seat cover F L, Burned, E - Replace	<b>300,00</b>
-------------------------------------	---------------





Spare wheel, Missing, E - Replace

153,60



Roof, Dent(s), Acceptable

0,00

*No pictures to display*

Wing F L, Dent(s), Acceptable

0,00

*No pictures to display*

Interior, Damaged, Acceptable

0,00



Seat cover F R, Burned, E - Replace

300,00



Rocker panel inner F L, Scratch(es), Forfeit

115,56



Door F R, Scratch(es), Acceptable

0,00

*No pictures to display*