



VOLKSWAGEN GOLF VII: 1RHT186

Vinnumber:	WVWZZZAUZH120059	Versionname:	1.2 TSI 63KW TRENDLINE
First Registrationdate:	2/01/2017	Fiscalpower:	
Expertise Mileage:	61154	Power Kw:	63
Bodytype:		Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2503
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
Windows electric F		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 H Steel				
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Hankook: 4 mm	Re.R.	Hankook: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	772,98
Bumper corner R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
SD card, Missing, E - Replace	275,00



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror glass L, Broken, E - Replace 18,00



Wing F R, Dent(s), LI - Repair and paint (complete) 268,18



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Remove lettering 0,00



Bumper F, Crack, LI - Repair and paint (complete) 211,80

