



LAND ROVER DISCOVERY SPORT: 1PDF628

Vinnumber:	SALCB2DN8GH615635	Versionname:	2.0 ED4 110KW SE 2WD
First Registrationdate:	9/06/2016	Fiscalpower:	
Expertise Mileage:	150840	Power Kw:	110
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2531
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Alarm	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/60/18/92 MS LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	754,56
-------------------	---------------

Tailgate, Scratch(es), It - Spot repair	115,56
---	---------------



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair 58,80



Bumper F, Deformed / Strained, Smart repair 110,64



Bumper Trim F, Deformed / Strained, E - Replace 109,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Broken, E - Replace 150,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper corner R R, Scratch(es), It - Spot repair 115,56



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display