



PEUGEOT Boxer 335: 1CNA636

Vinnumber:	VF3YCTMFB12138650	Versionname:	BOXER 335 B/F MWB HR L2H2 FAP 130PK
First Registrationdate:	9/01/2012	Fiscalpower:	
Expertise Mileage:	75513	Power Kw:	96
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV21
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Type of Tow bar
Radio multimedia	Tow bar fixed
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	No climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/70/15/109 S Steel			
Summer tyres:	Fr.L. Michelin: 4 mm	Fr.R. Michelin: 4 mm	
	Re.L. Bridgestone: 3 mm	Re.R. Bridgestone: 3 mm	

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 2172,51

Bumper F, Dent(s) and scratch(es), E - Replace 398,40





Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Worn, Acceptable 0,00



Bumper corner R L, Dent(s), Smart repair 110,64



Rearview mirror R complete, Broken, E - Replace 138,00



Windscreen, Stone chip(s), Windscreen repair 58,80



Door seal F L, Deformed / Strained, E - Replace 46,50



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Roof pillar L, Scratch(es), Acceptable 0,00

No pictures to display

Trunk door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 300,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner F L, Dent(s), LI - Repair and paint (complete) 115,56



Rocker panel inner F R, Dent(s), LI - Repair and paint (complete) 115,56



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 300,00



Mirror side blinker R, Broken, E - Replace 28,50



Bumper R, Broken, E - Replace 329,40

