



LU Audi sq5: LK5059

Vinnumber:	WAUZZZ8R3GA028882	Versionname:	3.0 TDI 230KW TIPTRONIC QUATTRO
First Registrationdate:	18/08/2015	Fiscalpower:	
Expertise Mileage:	190497	Power Kw:	230
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4333
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	255/40/21/92 MS LightMetal			
	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm

Assistance equipment

Total cost ex VAT	463,80
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Vanity mirror, Not original part, Forfeit

25,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s), Acceptable

0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper grille, Not original part, Acceptable

0,00



Rear window, Scratch(es), Acceptable

0,00



Tires, Worn, E - Replace

0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair

58,80

