



**HYUNDAI H350: 1TGC649**

Vinnumber:	<b>KMFAB17RPHK009262</b>	Versionname:	
First Registrationdate:	<b>26/10/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>48874</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>LCV29</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>235/65/16/92 H Steel</b>				
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

<b>Total cost ex VAT</b>	<b>1075,97</b>
<b>Trunk door R L, Dent(s), Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	
<b>Ignition key, Missing, E - Replace</b>	<b>150,00</b>
<i>No pictures to display</i>	
<b>Trunk door R R, Dent(s), LI - Repair and paint (complete)</b>	<b>250,00</b>



Bumper R, Scratch(es), Smart repair

110,64



Internal Boot Lining L, Crack, E - Replace

24,80



Roof, Dent(s), LI - Repair and paint (complete)

457,13



Inner seat cover L, Broken, E - Replace

24,60



Windscreen, Stone chip(s), Windscreen repair

58,80

