



OPEL VIVARO: 1LNT997

Vinnumber:	W0L3F7002FV635647	Versionname:	1.6CDTI 85KW EDITION SWB 2.7T
First Registrationdate:	30/10/2015	Fiscalpower:	
Expertise Mileage:	89694	Power Kw:	85
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2621
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	5		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Sun Roof electric	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	Tow bar fixed
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/65/16/92 H Steel				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2233,04
--------------------------	----------------

Bumper corner R L, Crack, E - Replace	149,00
--	---------------



Bumper F, Crack, Le - Replace and paint	575,25
--	---------------



Roof, Dent(s), Acceptable 0,00

No pictures to display

Trunk door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 370,00



Bumper trim R, Dent(s), E - Replace 108,26



Bumper corner R R, Crack, Le - Replace and paint 149,00



Rearlight R, Crack, E - Replace 91,50



Rearview mirror R complete, Broken, E - Replace 138,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 165,13



Rearlight L, Crack, E - Replace 91,50



Windscreen, Crack, E - Replace 395,40

